

Case Study
S. Ark. – N. La.

- **Historical Site**
- **Salt Water Disposal**

Site Condition

- **Sodic Soil**
- **Sandy Clay**
- **Top Soil Erosion**

EC 17 - 49

SAR 12 - 64

ESP 17 - 52

CEC 6 - 15

Treatment

- **Install drain system**
- **Deep plow and bulk soil**
- **Apply amendments**
- **Flush with water**

Amendments Applied

- ***DeSalt Plus***™
- ***DeSalt***™
- ***GeoRinse***™
- ***JumpStart***™

Test Seeding
Replanting of Native Grass

Time Lapse = 24 mos.

