

Case Study Gregg County, TX

- Historical Site
- Salt Water Disposal Pit

Site Condition

- Sodic Soil
- Top Soil Erosion
- Sandy Clay

EC 12
SAR 27
ESP 50
CEC 5

Treatment

- Deep plow and bulk soil
- Apply amendments
- Flush with water

Amendments Applied

- *DeSalt*™
- *DeSalt Plus*™
- *GeoRinse*™

Re-seed with native grass

Time Lapse = 12 mos.

