

Case Study Harris County, Texas

- Historical Site
- Salt Water Disposal System

Site Condition

- Φ Sodic Soil
- Φ Heavy Clay

EC	77
SAR	125
ESP	93
CEC	40

Treatment

- Φ Deep plow and bulk soil
- Φ Install drain pattern with bulking materials
- Φ Applied amendments
- Φ Irrigate

Amendments Applied

- Φ *DeSalt*™
- Φ *DeSalt Plus*™
- Φ *GeoRinse*™

Re-seed with native grass

Time Lapse = 18 mos.

