

Case Study
Terrebonne Parish, Louisiana

- **Historical Site**
- **Salt Water Disposal Pit**

Site Condition

- **Sodic Soil**
- **Heavy Clay**

EC 20
SAR 30
ESP 43
CEC 46

Treatment

- **Disc soil**
- **Apply amendments**
- **Flush with water**

Amendments Applied

- ***DeSalt™***
- ***GeoRinse™***

Test Seeding

Re-seed with native grass

Time Lapse = 18 mos.

